



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **GB/SIR/QAR09.0010/17** Page 1 of 1

QAR Free Ref. No.: **80247963/80247964/80247965** Status: **Issued**

Details of change: **Surveillance Audit** Date of issue: **2025-07-24**

Location(s) audited: **Dixon Bayco** Valid until: **2027-06-30**  
7280 Union Center Boulevard  
West Chester  
OH 45014  
**United States of America** Audit date: **2025-06-05**

Issuing ExCB: **CSAE - CSA Group Testing UK Ltd**

Manufacturer: **Dixon Bayco**  
7280 Union Center Boulevard  
West Chester  
OH 45014

Location of Manufacturer: **United States of America**

Product information: **Liquid Level Sensors**

Type of protection: **Ex ia, d.**

Related QARs:

<a href="#">GB/SIR/QAR09.0010/00</a>	<a href="#">GB/SIR/QAR09.0010/01</a>	<a href="#">GB/SIR/QAR09.0010/02</a>
<a href="#">GB/SIR/QAR09.0010/03</a>	<a href="#">GB/SIR/QAR09.0010/04</a>	<a href="#">GB/SIR/QAR09.0010/05</a>
<a href="#">GB/SIR/QAR09.0010/06</a>	<a href="#">GB/SIR/QAR09.0010/07</a>	<a href="#">GB/SIR/QAR09.0010/08</a>
<a href="#">GB/SIR/QAR09.0010/09</a>	<a href="#">GB/SIR/QAR09.0010/10</a>	<a href="#">GB/SIR/QAR09.0010/11</a>
<a href="#">GB/SIR/QAR09.0010/12</a>	<a href="#">GB/SIR/QAR09.0010/13</a>	<a href="#">GB/SIR/QAR09.0010/14</a>
<a href="#">GB/SIR/QAR09.0010/15</a>	<a href="#">GB/SIR/QAR09.0010/16</a>	

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

<a href="#">IECEX CSA 21.0036X issue: 0</a>	<a href="#">IECEX SIR 09.0013X issue: 0</a>	<a href="#">IECEX SIR 09.0013X issue: 1</a>
<a href="#">IECEX SIR 09.0013X issue: 2</a>	<a href="#">IECEX SIR 09.0013X issue: 3</a>	<a href="#">IECEX SIR 09.0013X issue: 4</a>
<a href="#">IECEX SIR 09.0013X issue: 5</a>	<a href="#">IECEX SIR 09.0013X issue: 6</a>	<a href="#">IECEX SIR 09.0014X issue: 0</a>
<a href="#">IECEX SIR 09.0014X issue: 1</a>	<a href="#">IECEX SIR 09.0014X issue: 2</a>	<a href="#">IECEX SIR 09.0014X issue: 3</a>
<a href="#">IECEX SIR 09.0014X issue: 4</a>	<a href="#">IECEX SIR 09.0014X issue: 5</a>	<a href="#">IECEX SIR 09.0014X issue: 6</a>
<a href="#">IECEX SIR 09.0015X issue: 0</a>	<a href="#">IECEX SIR 09.0015X issue: 1</a>	<a href="#">IECEX SIR 09.0015X issue: 2</a>
<a href="#">IECEX SIR 09.0015X issue: 3</a>	<a href="#">IECEX SIR 09.0015X issue: 4</a>	<a href="#">IECEX SIR 09.0016X issue: 0</a>
<a href="#">IECEX SIR 09.0016X issue: 1</a>	<a href="#">IECEX SIR 09.0016X issue: 2</a>	<a href="#">IECEX SIR 09.0016X issue: 3</a>
<a href="#">IECEX SIR 09.0017X issue: 0</a>	<a href="#">IECEX SIR 09.0017X issue: 1</a>	<a href="#">IECEX SIR 09.0017X issue: 2</a>
<a href="#">IECEX SIR 09.0017X issue: 3</a>	<a href="#">IECEX SIR 09.0017X issue: 4</a>	<a href="#">IECEX SIR 14.0100X issue: 0</a>
<a href="#">IECEX SIR 14.0100X issue: 1</a>	<a href="#">IECEX SIR 14.0100X issue: 2</a>	<a href="#">IECEX SIR 19.0052X issue: 0</a>
<a href="#">IECEX SIR 19.0052X issue: 1</a>	<a href="#">IECEX SIR 19.0052X issue: 2</a>	<a href="#">IECEX SIR 19.0052X issue: 3</a>
<a href="#">IECEX SIR 19.0052X issue: 4</a>		

Comments: